



Field Bulletin

- STS 4.0
- Library file update

Bulletin #:	FG00906
Bulletin Date:	July 20, 2006
Subject:	STS 4.0 library file update
Affected Model(s):	SCXXXX

Summary:

The purpose of this bulletin is to inform you that a library update has been released for the STS V4.00. MEI recommends that this update be implemented only if you have STS V4.0

Detail:


This update installs a new version of the SCL Library (V4.01), which is one of the major components used by STS.

The following issues were resolved with this release:

- When reading from a connected bill acceptor, the note description or values were not shown.
- .xcf file software downloads to the SC series bill acceptor using V1.06 Boot code would cause the SC series to lock up.

Action:

This update takes the form of a single executable file. It can be downloaded from the MEI technical website (www.meitechnical.com) under the For customers section.


- Click on the Gaming and then Gaming products buttons.
- Scroll down to the miscellaneous section and download  setup.exe

After the install is complete you can check to make sure the new library file was loaded properly by going to Help tab of the STS program and select about.



Questions should be directed to MEI Technical Support at 1-800-345-8172 or our web site: www.meiglobal.com

The following screen will appear. Look to see that the Support component Library section has been updated to V4.01.



	Ver	Part #
Cashflow STS Installation	V4.00	792153400
Cashflow STS Executable	V4.00	791505400
Support Component Library	V4.01	791472401
Support Database	V3.00	791465300
Mars USB DLL	V1.20	791454120

Any questions can be answered by your local MEI or AESI representative.

AESI Contact Information

6285 S. Mojave Road, Suite E
Las Vegas NV. 89120
Toll free: 866-736-AESI (2374)
Phone: 702-597-4840

Questions should be directed to MEI Technical Support at 1-800-345-8172 or our web site: www.meiglobal.com